North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

1 2 3

##(Include Double Pound for comments, not form fields)

##Report Form ID Ship Operator Name Vessel Name
2 Nikolaos Kontos Seaways Fran

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice Marshall Islands 9213313 13-Mar-18 Galveston LZ

SW Pass IZ

8

Dos Bocas, Mexico

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption Chalmette, Lousiana

10

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA Terminal N/A 10-Feb-18

14	15	16
L T	13	10

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion 16:00 2.31% 40

Name of First POC Compliance Fuel Oil Available at First POC?

New Orleans Yes Plan to Bunker Compliant Fuel Oil at First POC?

Yes

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

2 SW pass LZ non available until 25th

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? n/a n/a

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months? Estimated March 25, 2018 Approx 2300 yes

28	29

Number of Separate Visits to the ECA	Number of Ports visited in the ECA
11	19

Previously submitted ECA0100 forms? yes but has been rescinded due to fact vessel did not switch over to non compliant fuel

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail 1 Sigma Tankers Inc

Bunkersgroup@Heidmar.com

33

Designated Corporate Official Phone Number 12036622600 Description of Actions to Achieve Compliance

Vessel was alongside Chalmette Refinery - bunkers are in place for Delivery, however Terminal will not allow alongside Fonar filed and granted - Terminal would not allow non compliant fuel alongside

Barge company is ready to delivery alongside but Terminal will not allow

when vessel was forced to vacate the berth thre were no available anchorages in the River as per pilots/agents earliest supply offshore is 25th of March

vessel presently has 19 mt of LSMGO aboard is inadequate to perfom operation with Compliant fuel vessel will switch to non compliant fuel to complete sts operation and transit up the river to receive LSMGO where vessel will receive as soon as anchored - and switch over prior to berthing for discharge